
Designing for 3D printing

CAD software





The interface




Navigating the 3-dimensional space

Moving around

Zoom in and out using the scroll wheel

Pan & Tilt

- Right click and drag to change the aspect of your view or
- Click and drag the Cube device to rotate you view angle
- If you get lost click the home icon and it will take you back to the default view





Select


- Using the left click (hold shift select multiple objects)
- Or left click and drag a selection box around multiple objects


Left button

-click to select (hold SHIFT(to select multiple objects)

or


 -click & drag a box select to select multiple multiple






Resizing

- left click and drag the black or white handles to resize the your shapes.
- Hold the SHIFT key to constrain proportions.
- Left click and drag the black cone to change the elevation of your in relation to the work plane






Moving

You can nudge a selected object around the x & y axes with the arrow keys

Rotate

Left click and drag the curly one of the 3 arrows to rotate an object. Once the angle highlighted you an type in an angle too.*


*it can be difficult to realign an object's angle once you've moved it so be deliberate with these changes





Ruler

 Drag the ruler out onto the workplane to resize or arrange shapes using typed in dimensions.









Make a complex shape


Grouping solids and holes

- You can make complex shapes by combining and subtracting the primitive (basic) shapes using the group tool.
- Select the objects you want to combine
- And then hit the group button

Make a complex shape in 4 steps




Start with 2 shapes




Select one shape and make it a hole



now select both by dragging a box around them




and hit the group button



Da Na!


Export your job for printing



select the parts of your design you want to print




hit the export button




and select STL

Slicing with PrusaSlicer

Slicing



Slicing



Scale or resize using percentages or dimensions




padlocck icon - constrains proportion click to unlock

Hit slice to preview how your settings will pan out

Slice now

select the volume of internal fill matrix added to the




Print Resolution

Print settings :

select print quality / layer thickness

· (0)

Infill





Custom Support in PrusaSlicer 1 Use the Paint on Support tool 3 Da Da!

1 Use the Paint on Support tool




2 Select for Support enforcers only





4 Inspect and other print features using the layer /time ruler



Export from PrusaSlicer

Whats it going to cost in terms of Filament and time?

If your happy with these costs when measured against the resolution, infill, support settings...?


Sliced Info	
Used Filament (g) (including spool)	5.87 (270.87)
Used Filament (m)	1.97
Used Filament (mm³)	4732.64
Cost	0.15
Estimated printing time: - normal mode - stealth mode	1h3m 1h4m

Export G-code

Export your print job to an SD card


Print-in-Place articulated model in 7* easy steps


*some patience required



















Export your model from TinkerCAD & open it in PrusaSlicer adding support around your connectors

Use the Paint-on-support tool to add support around the connectors. The support (shown in green) will hold the connector during printing